

Local 429: Tool List for Trade Shows



REQUIRED TOOLS:

- Tool Box or Tool Bag



- 16 oz. Claw Hammer



- Pliers: (a) Slip Lock (b) Vise Grip (c) Wire Cutters (need all 3)



- Pry Bar: (a) Flat Bar (b) Nail Bar (Must have Flat Bar Nail Bar/Puller Helpful)



- Crescent/Adjustable Wrench and T Wrenches 30mm & 5mm, the Corner Wrench (Can be bought from Freeman on sight for \$1.00)



- 25 foot tape measure – US



- Stanley Retractable Utility Knife (preferred) or the Double-edge Carpet one or the other along with the Loop Pile or (b) the Push Knife / Top Cutter (preferred)



- Wrenches: 3/16" to 1" Standard and Metric – Box or Open End



Local 429: Tool List for Trade Shows



- Socket Set: Standard and Metric- 1/4" & 3/8" drive, size 3/16" to 1"



- Screw Drivers: Phillips and Regular/Slotted or (you can buy one screwdriver that has six or so bits attached to it such as several interchangeable tips Regular, Philips, Allen and or Star)



- Staple Gun: Arrow JT 21 or any stapler that holds the JT 21 staples



- Allen Set: US and Metric



- Chalk Box and Chalk



- Torpedo Level



- Combo Square



- Cordless Drill



- Assortment pack of driver tips (Phillips, Slotted, Star, Allen, etc.)

